



LM2500+/G4 TORQUE SHAFTS



Rotable Exchange



Specialist Repairs



Field Support



Fixed Prices



Rapid TAT



Latest Technology



Warranty

- · OEM approved torque shaft overhaul service provider
- OEM Specifications, optimised for precision repairs
- LM2500+ Part Numbers L50519G07-G19
- LM2500+G4/G5 Part Numbers L59048G05-G07
- MRO facilities operating under a ISO 9001:2015
- All works performed in accordance with OEM standards, specifications, and manuals
- Fixed price inspections
- 5 day turnaround, subject to parts availability
- Serviceable inventory on hand including bearings and rod end bearings
- Specialist repairs increasing part life & reducing costs
- Rotable Torque shafts reduced outage time
- Service Bulletin upgrades
 - SB248 Torque Shaft FWD Bearing Improvement
 - SB249 Torque Shaft AFT Bearing Improvement
 - SB290 Torque Shaft Improvement Damper Links
- Field support available for removal & replacement.

www.fwmarsh.com

energy@fwmarsh.com

